## MARION COUNTY SURVEYOR'S OFFICE

DEBRA S. JENKINS MARION COUNTY SURVEYOR SECTION CORNER RECORD SEC. 27 TWN.  $15_{\text{N}}$  RNG.  $4_{\text{E}}$ 

BRYAN F. CATLIN, PLS TECHNICAL SUPERVISOR

Date: 9-26-09

Party Chief: Wilcoxen

Crew: Finney


Type of Marker: Rebar fd

Method of Establishment: County: 1-26-1999


IN S.P.C. E Zone, NAD 83


Name: 15042705 N: 496 141.329 0(m) E: 65 149.559 0(m) Section Line 5500





Amtrack property





Corner referenced by Cantrell of Paul Cripe Engineers on 12/3/1974 and called a stone found 3.5" down with a rebar set over stone. Corner was referenced by Wilcoxen on 5/12/77 and called a rebar. Corner referenced by Gries on 11/29/88 and called a rebar. Corner was verified by Jones of United Consulting on 4/2/90 and called a rebar. Corner referenced by Kiste on 8/5/96 and called a 3/4" rebar. Corner referenced by Wilcoxen on 1/26/1999 and called a rebar. Corner was referenced by Wilcoxen on 5/8/2004 and called a rebar. Corner referenced by Wilcoxen on 9/26/09 and called a rebar.

		T. C.
REF.	DISTANCE	DESCRIPTION
1.	50.10'	Top nut of fire hydrant
2.	25.06'	Due S to RR spike (C/L of Garstange)
3.	95.12'	Mag nail w/brass washer SE PwP #627-674 3" up
4.	55.05'	Mag nail w/brass washer NW PwP #143-674 18" up
5.	0.7'	Due N to face of fence line

THIS CORNER POSITION REPRESENTS A "TITLE" CORNER AND MAY NOT NECESSARILY REPRESENT THE POSITION BASED ON RECORD CORNERS